Declassified in Part - Sanitized Copy Approved for Release 2013/08/15 : CIA-RDP78-03424A001300080002-9



ORIO DEMP PATE 8 MAY BY 0/8373

ORIO DEMP 23 GPI 56 TYPE 0/

ORIO CLASS 4 FACES 3 REV CLASS C

JUST 22 NEXT REV 20/0 AUTH: HG 16-2

RACINE, WISCONSIN

December 21, 1953

Via: AIR MAIL - SPECIAL DELIVERY

Subject: Speed Reducer

Dear

50X1 50X1 50X1

A few fast lines to let you know that we believe we have arrived with a satisfactory speed reducer for use with the hand cranked generator.

You will recall that we had proposed a spring type torque drive to cushion the terrific load impact. This was tried and thrown out within about thirty seconds. It provided nothing in the way of cushion; in fact, we lost several components during this short time of operation.

Our next step was to try something we have been tossing around for some time, but for some unknown reason we just continued to toss it until our sad experience with the spring.

This "revolutionary" approach may not meet with your approval and that is why we are writing you at this time. It has been suggested that a belt drive might be frowned upon, and frankly, that is just what we are using.

The drive between the generator and the speed reducer consists of two, five inch pulleys and an appropriate "B" section V-belt. An over-center belt tension lever will be provided to facilitate disengagement for engine starting as well as to keep the belt under proper tension.

The overall width and heighth of the belt guard (formerly chain guard) will be increased approximately one inch, however, this assembly still remains within the confines of the engine and generator. Performance is all that one could ask for, it is smooth and positive, and we feel that it will be somewhat less costly to build.

CONFIDENTIAL

-2-

We would appreciate it very much if you would review this new approach and let us know whether or not it meets with your approval. In the meantime, we will continue testing the unit.

## Very truly yours,

JACOBSEN MANUFACTURING COMPANY

50X1

50X1

The above there was inspected at

Jacobsen plant on 5/ Dec & 3 wet a peaced to be warning

ok. Jacobsen will fobricate a better model for demonstrating

about The end of January \$4

50X1

CON DOMAN

